

## Annexure D

### BUILDING SAFETY CERTIFICATE

NO. 570

Dated. 12.04.2024

It is certified that the existing building DAUD ALAM PUBLIC SCHOOL (A SCHOOL OF STATUS) at Barhoga Kothi, Jamo Bazar, Siwan in having block (s)/Floor as per details below:


Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor (s) in the Block	<u>G+1</u>					

The building is owned/occupied by DAUD ALAM PUBLIC SCHOOL (A SCHOOL OF STATUS) (Name of the institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Building Division, Siwan (Name of Department/Govt.) on 10.04.2024 (date of inspection) in the presence of Mossarrat Perween, Bhada, Jamo Bazar, Siwan (Name and addresses of the Manager/secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 12.04.2024 for a period of 01 (One) Years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. The work has been completed to my best satisfaction.*
- 2. The workmanship & all the materials have been used strictly in accordance with general and detailed satisfaction.*
- 3. The building is structurally sounded safe and hygienic.*
- 4. Hence, is fit for use how in with DAUD ALAM PUBLIC SCHOOL (A SCHOOL OF STATUS) IS running.*

Issued on 12.04.2024 at Siwan by

Strike out whichever is not applicable. In Case of block is more than six use separate sheet for detail.



*M. Mithlesh Kumar*  
12/04/24  
(Er. Mithlesh Kumar)  
Executive Engineer  
Building Division, Siwan  
Executive Engineer  
Building Division  
Siwan

कार्यपालक अभियंता का कार्यालय,  
भवन प्रमण्डल, सीवान।

पत्रांक 5703195

दिनांक 12.04.2024

प्रेषक,

ई0 मिथलेश कुमार,  
कार्यपालक अभियंता,  
भवन प्रमण्डल, सीवान।

सेवा में,

Director,  
Daud Alam Public School (A school of Status)  
Barhoga kothi Jamo Bazar,  
Siwan 841413

विषय:-

DAUD ALAM PUBLIC SCHOOL (A School of Status), Barhoga Kothi,  
Jamo Bazar, Siwan का भवन सुरक्षा प्रमाण पत्र निर्गत करने के संबंध में।

प्रसंग:-

आपका पत्रांक शून्य दिनांक 06.04.2024 एवं सहायक अभियंता, भवन अवर प्रमंडल संख्या-01,  
सीवान का पत्रांक 66 दिनांक 10.04.2024


महाशय,

उपर्युक्त विषयक आपके प्रासंगिक पत्र के आलोक में कहना है कि उक्त विद्यालय का निरीक्षण श्री ब्रजेश कुमार पटेल, सहायक अभियंता, भवन अवर प्रमंडल संख्या-01, सीवान द्वारा किया गया एवं निरीक्षणोपरांत उनके द्वारा समर्पित प्रतिवेदन अनुसार स्थूल निरीक्षण में भवन की स्थिति सामान्य परिस्थिति में ठोस है।

अतः सहायक अभियंता द्वारा प्राप्त जॉच प्रतिवेदन के आधार पर पत्र निर्गत की तिथि से एक वर्ष तक विद्यालय भवन को स्थूल निरीक्षण के आधार पर सामान्य परिस्थिति में पठन-पाठन हेतु उपयुक्त होने का प्रमाण पत्र "Annexure D" निर्गत किया जाता है।

अनुलग्नक:-

1. सहायक अभियंता का जॉच प्रतिवेदन की छायाप्रति।
2. "Annexure D"



विश्वासभाजरी  
12/04/24  
कार्यपालक अभियंता,  
भवन प्रमण्डल, सीवान।

पत्रांक - 62

दिनांक - 10/04/2024

प्रेषक:-

सहायक अभियंता  
भवन अवर प्रमोडल  
सं-02, सीवान

सेवा में,

कार्यपालक अभियंता  
भवन प्रमोडल, सीवान

विषय:- भवन दुखा प्रमाण पत्र निर्गत करने के संबंध में,

प्रसंग:- Director, DAVD ALAM PUBLIC SCHOOL, Barhoga Kothi,  
Jamo Bazar, Siwan का पत्रांक शुन्य दिनांक 06/04/2024


महाराज,

उपरोक्त प्रासंगिक विषय के संबंध में कहना है कि मेरे

द्वारा DAVD ALAM PUBLIC SCHOOL, Barhoga Kothi, Jamo  
Bazar, Siwan के भवन का स्कूल निरीक्षण किया गया। स्कूल  
निरीक्षण में स्कूल भवन सामान्य परिस्थिति में देखे हैं।

अतः सूचनाएँ एवं आवश्यक कार्रवाई हेतु सप्रति।

सुस्त  
10/04/24



विश्वनाथ शास्त्री

10/04/2024

सहायक अभियंता

भवन अवर प्रमोडल

सं-02, सीवान।